

County Surveyor's Record, Douglas County, Oregon

Subdivision of T. 24 S., R 9 W.

CHAINS

mkd. T 24 S R 9 W S 21 B T.

A fir, 20 ins. dia., bears S.5°E., 31 lks. dis.

mkd. T 24 S. R 9 W S 28 B T.

A fir, 20 ins. dia., bears S.80°W., 13 lks. dis.

mks. T 24 S R 9 W S 29 B T.

A fir, 20 ins. dia., bears N.18°W., 71 lks. dis.

mkd. T 24 S R 9 W S 20 B T.

Land, mountainous.

Soil, shallow; 3rd rate.

Timber, fir, cedar and hemlock.

Undergrowth, rhododendron, vine maple, salal, huckleberry
and Oregon grape.Land, mountainous, heavily timbered or covered with
dense undergrowth, 80.00 chs.

August 30, 1905

At the cor. of secs. 20, 21, 28 and 29.

Thence I run

N.89°48'E., on a random line bet. secs. 21 and 28.

40.00 Set temp. $\frac{1}{2}$ sec. cor.80.36 Intersect N. and S. line, 4 lks. N. of cor. of secs. 21,
22, 27 and 28.

Thence I run

S. 89°50'W., on a true line bet. secs. 21 and 28

Over mountainous land through heavy timber and dense
undergrowth.

1.00 A ridge, sloping N.

6.70 Bear camp Creek, 40 lks. wide, 100 ft. below sec. cor;
course NE.

Ascend from Creek.

8.20 Foot of steep rocky ledge, bears N. and S., very
difficult and dangerous to ascend, in order to pass
which I offset South, 1.71 chs.; then run on offset
line S.89°50'W.,