

Resurvey of East Boundary, T. 25 S., R 2 W., W.M.

CHAINS

A Fir, 18 ins. diam., bears S.63*E., 55 lks. dist.,
marked $\frac{1}{2}$ S 6 B T.

A Fir, 8 ins. diam., bears S.79*W., 75 lks. dist.,
marked $\frac{1}{2}$ S 1 B T.

and ascend 300 ft. to

102.00 Summit of hill, bears E and W and descend 100 ft. to

113.40 Intersect the North boundary of township 14.05 chs. E
of the SW cor. of Tp. 24 S R 1 W which is a basalt
stone 10x10x5 ins. above ground, marked and witnessed
as described by the surveyor general.

At the point of intersection, I set a basalt stone
16x9x8 ins., 11 ins. in the ground for closing cor.
of Tps. 25 S Rs. 1 and 2 W., marked C C on S face,
with 6 notches on E and W faces, from which

A Chinquapin, 6 ins. diam., bears S.45*E., 44 lks.
dist., marked C C T 25 S R 1 W S 6 B T.

A Dogwood, 5 ins. diam., bears S.18*W., 39 lks.
dist., marked C.C T 25 S R 2 ^{S /} W _^ B T.

Land, mountainous.

Soil, 2nd rate clay loam.

Timber, fir, hemlock, cedar, and pine.

Undergrowth, chinquapin, rhododendron, dogwood, cherry
and willows.

Mountainous land or land covered with heavy timber or
dense undergrowth, 113.40 chs.

June 23, 1900

GENERAL DESCRIPTION:

The townships bounded by this line are both very
rough and mountainous.

They are both well watered by numerous springs and
streams.

Both townships are heavily timbered.

They should be subdivided.

Hezekiah H. Johnson,

U.S. Deputy Surveyor.