

32  
County Surveyor's Record, Douglas County, Oregon

South Boundary, T 25 S., R 1 W., W.M.

CHAINS	
	And continue ascent.
47.00	Summit of ridge bears NW and SE about 600 ft. above sec. cor., and descend 100 ft. to
62.00	Ravine, course S., thence along S slope to
84.50	Descend into rocky canyon 100 ft. to
90.00	Brook, 4 lks. wide, flows S., and ascend 100 ft. to
94.00	Out of canyon, thence along S slope.
120.00	Foot of hill bears NE and SW., and ascend 150 ft. to
131.00	Top of hill bears NE and SW., and enter bench.
134.50	Brook, 5 lks. wide, flows SE and ascend 50 ft. to
136.20	Intersect the W boundary of Tp. 6.75 chs., S of the $\frac{1}{4}$ sec. cor. on the E boundary of sec. 36, T 25 S R 2 W., and at the point of intersection, I set a basalt stone, 18x11x6 ins., 12 ins. in the ground for closing cor. of secs. 6 and 31, marked C C., with 6 notches on the N and S edges, from which A Fir, 24 ins. diam., bears N.58°E., 63 lks. dist., marked C C T 25 S R 1 W S 31 B T. A Fir, 6 ins. diam., bears S.71°E., 45 lks. dist., marked C C T 26 S R 1 E S 6 B T.
	Land mountainous.
	Soil, clay loam, 3rd rate.
	Timber, fir, pine, hemlock and cedar.
	Undergrowth, maple, willow, hazel, fir, hemlock, arbutus, rhododendron and spicewood.
	Mountainous land, or land covered with heavy timber or dense undergrowth, 136.20 chs.

July 30th, 1900

GENERAL DESCRIPTION:

This township is very rough and mountainous throughout. The township is well watered, and with the exception of the south tier of sections, which have been partly burned over, is well timbered. The township should be subdivided.

Hezekiah H Johnson  
U.S. Deputy Surveyor.