

## County Surveyor's Record, Douglas County, Oregon

Subdivisions T.25 S., R 1 W., W.M.

CHAINS	
	S.89*56'E., on a random line bet. secs. 14 and 23.
40.00	Set a temp. $\frac{1}{4}$ sec. cor.
80.30	Intersect N and S line 16 lks. S of the cor. of secs. 13, 14, 23, and 24.
	Thence I run
	S.89*57'W., on a true line bet. secs. 14 and 23.
	Over mountainous land, through heavy timber and dense undergrowth.
	Descend steep rocky hill.
6.10	Spring branch, 1 lk. wide, flows SW.
10.30	Spring branch, 1 lk. wide, flows SW.
22.25	Foot of mountain, bears N and S., about 500 ft. below sec. cor., enter bottom.
35.80	Canton creek, 70 lks. wide, flows S.10*E.
40.15	Set a yew post, 3 ft. long, 3 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 14 on N., S 23 on S faces, from which
	An Alder, 17 ins. diam., bears N.72*W., 8 lks. dist., marked $\frac{1}{4}$ S 14 B T.
	A Hemlock, 8 ins. diam., bears S.15*W., 8 lks. dist., marked $\frac{1}{4}$ S 23 B T.
42.40	Foot of hill bears N and S., leave bottom and ascend 400 ft. to
80.30	The cor of secs. 14, 15, 22, and 23.
	Land mountainous.
	Soil, clay loam, rocky, 2nd to 4th rate.
	Timber, fir, hemlock, cedar, yew, alder and arbutus.
	Undergrowth, fir, cedar, maple, arbutus, oak and hazel.
	Mountainous land, or lands covered with heavy timber or dense undergrowth, 80.30 chs.

Aug. 9th, 1900

N.2'W., bet. secs. 14 and 15.

Over mountainous land through heavy timber and dense undergrowth.