

101  
County Surveyor's Record, Douglas County, Oregon

Retracement of the North Boundary of T. 26 S., R 1 W.

CHAINS	<p>Timber, fir.</p> <p>Undergrowth, hazel, vinemaple, fir.</p> <p style="text-align: right;">July 25, 1910</p>
6.75	<p>At the cor. of secs. 32 and 33, T 25 S R 1 W.</p> <p>Thence I run</p> <p>West on S bdy., sec. 32, T 25 S R 1 W.</p> <p>Over mountainous land, heavily timbered and covered with dense undergrowth.</p> <p>Descend SW slope.</p> <p>Creek, 1 lk. wide, course SE., ascend E slope.</p>
30.00	<p>Ridge bears N and S.</p> <p>Descend W. slope.</p>
39.85	<p>The <math>\frac{1}{4}</math> sec. cor., which is a sandstone, 5x12x4 ins. above ground, firmly set, marked and witnessed as described by the surveyor general.</p> <p>I re-establish this cor. in its original position as the <math>\frac{1}{4}</math> sec. cor. on S bdy., sec. 32, T S R 1 W., only, as follows:</p> <p style="padding-left: 40px;">Stone above described, already set, from which</p> <p style="padding-left: 80px;">A Fir, 48 ins. diam., bears N.41<math>\frac{1}{2}</math>*E., 130 lks. dist., marked <math>\frac{1}{4}</math> S 32 B T.</p> <p style="padding-left: 80px;">A Maple, 4 ins. diam., bears N.21<math>\frac{1}{2}</math>*W., 62 lks. dist., marked <math>\frac{1}{4}</math> S 32 B T.</p> <p>I obliterate marks on former bearing tree referring to sec. 5.</p> <p>The course of this line is West and the distance is 39.85 chs.</p> <p>From the <math>\frac{1}{4}</math> sec. cor. I run</p> <p>West on S bdy., sec. 32, T 25 S R 1 W.</p> <p>Descend SW slope.</p>
4.00	<p>Ravine, course SW.</p>
12.25	<p>Creek, 5 lks. wide, course S. Ascend E. slope</p>
16.25	<p>Ridge point descending S.</p> <p>Descend SW slope.</p>
19.90	<p>Fairview Creek, 8 lks. wide, course S.20*E.</p> <p>Ascend E slope.</p>