

County Surveyor's Record, Douglas County, Oregon

East Boundary of T. 25 S., R. 3 W., W. M.

CHAINS	<p>A fir, 24 ins. diam., bears N.61°E., 57 lks. dist., marked T 25 S R 2 W S 6 B T.</p> <p>A fir, 24 ins. diam., bears S.69°E., 13 lks. dist., marked T 25 S R 2 W S 7 B T.</p> <p>A fir, 36 ins. diam., bears S.10°W., 19 lks. dist., marked T 25 S R 3 W S 12 B T.</p> <p>A fir, 40 ins. diam., bears N.21°W., 33 lks. dist., marked T 25 S R 3 W S 1 B T.</p> <p>Land mountainous. Soil 4th rate. Densely covered with forest of fir, hemlock, cedar, pine, maple, alder, yew, chinquapin, laurel & dogwood. Thick undergrowth of sallal, vine maple, hazel, manzanita, fir, laurel, salmonberry & huckleberry.</p>	
	<p>North on random between secs. 1 & 6.</p> <p style="text-align: right;">Va. 21½°East.</p> <p>Through heavy timber.</p>	
13.20	A canyon, course E & W.	-500
30.15	A hemlock, 18 ins. diam.	
32.00	A ridge, course E & W.	+700
40.00	Set temp. ¼ sec. cor.	
49.30	A fir, 40 ins. in diam.	
78.52	<p>Intersect S boundary T. 24 S., R. 3 W., 2.18 chs. W of cor. to Tps. 24 and 25 S., R's 2 & 3 W. which is a cedar post 4 ins. sq., firmly set in the ground marked T 24 S S 31 on NE., R 2 W S 6 on SE., T 25 S S 1 on SW and R 3 W S 36 on NW faces, with 6 notches on each edge, from which,</p> <p>A hemlock, 24 ins. diam., bears N.70°E., 26 lks. dist., marked T 24 S R 2 W S 31 B T.</p> <p>A hemlock, 16 ins. diam., bears S.15°E., 40 lks. dist., marked T 25 S R 2 W S 6 B T.</p> <p>A hemlock, 20 ins. diam., bears S.20°W., 24 lks. dist., marked T 25 S R 3 W S 1 B T.</p>	