

County Surveyor's Record, Douglas County, Oregon

Subdivisional and Exterior Lines of T. 25 S., R. 2 W., W. M.

CHAINS	Mountainous land or land covered with heavy timber or dense undergrowth. 80 chs. June 28th, 1900
	Thence 1 run, East on a random line between secs. 24 and 25.
40.00	Set temp. $\frac{1}{4}$ sec. cor.
80.14	Intersect the E. Boundary of Twp. 21 lks. S of the cor. of secs. 19, 24, 25 and 30.
	Thence 1 run, S.89°51'W., on a true line between secs. 24 and 25. Over mountainous land, through heavy timber and dense undergrowth.
	Ascend 400 ft. to
32.00	Top of ascent bears N and S. Thence over rolling bench land.
40.07	Set a basalt stone 18 x 14 x 9 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face, from which, A cedar, 20 ins. diam., bears N.44°E., 10 lks. dist., marked T 25 S R 2 W S 24 B T. A hemlock, 18 ins. diam., bears S.50°W., 4 lks. dist., marked T 25 S R 2 W S 25 B T.
65.29	Spring branch, 2 lks. wide, in ravine 30 ft. deep, flows NW.
80.14	The cor of secs. 23, 24, 25 and 26. Land rolling and mountainous. Soil clay loam, 2nd rate. Timber fir, hemlock, cedar and pine. Undergrowth rhododendron, vine maple, fir and hemlock. Mountainous land or land covered with heavy timber or dense undergrowth. 80.14 chs.
	N.1°W., between secs. 23 and 24. Over rolling ground, through heavy timber and dense undergrowth.
	Descend 50 ft. to
8.75	Spring branch, 3 lks. wide, flows W.
19.55	Spring branch, 1 lk. wide, flows W.