

County Surveyor's Record, Douglas County, Oregon  
33

Subdivisional and exterior Lines of T. 25 S., R. 2 W., W.M.

CHAINS	<p>Mountainous land or land covered with heavy timber or dense undergrowth. 80 chs.</p>
	<p>N. 89° 58' E. on a random line between secs. 11 and 14.</p>
40.00	Set a temp. $\frac{1}{4}$ sec. cor.
80.10	Intersect N. and S. line 15 lks. N. of the cor. of secs. 11, 12, 13 and 14.
	Thence I run,
	N. 89° 56' W. on a true line between secs. 11 and 14.
	Over rolling ground, through heavy timber and dense undergrowth.
14.17	Spring branch, 1 lk. wide, flows N.
24.16	Spring branch, 1 lk. wide, flows N.
28.00	Descend 60 ft. to
32.00	Brook, 6 lks. wide, flows N. and ascend along steep NE slope.
40.05	Set a basalt stone 20 x 8 x 5 ins., 15 ins. in the ground for $\frac{1}{2}$ sec. cor. marked $\frac{1}{4}$ on N. face, from which
	A cedar, 14 ins. diam., bears N. 25° E., 10 lks. dist., marked $\frac{1}{4}$ S 11 B T.
	A yew, 10 ins. diam., bears S. 31° E., 13 lks. dist., marked $\frac{1}{4}$ S 14 B T.
43.06	Spring branch, 1 lk. wide, flows N.
65.00	Spur, slopes N. 150 ft. above brook and descend 150 ft. to
80.10	the cor. of secs. 10, 11, 14 and 15.
	Land rolling and mountainous.
	Soil clay loam, 2nd rate.
	Timber fir, hemlock, cedar, pine and yew.
	Undergrowth vine maple, fir, rhododendron, chinquapin and hemlock.
	Mountainous land or land covered with heavy timber or dense undergrowth. 80.10 chs.

July 5th, 1900.