

## County Surveyor's Record, Douglas County, Oregon

35

Subdivisional and exterior Lines of T. 25 S., R. 2 W., W. M.

CHAINS

Land mountainous and level.

Soil clay loam, 2nd rate.

Timber fir, hemlock, maple, cedar and pine.

Undergrowth vine maple, fir, hemlock, rhododendron and chinquapin.

Mountainous land or land covered with heavy timber or dense undergrowth. 80 chs.

S. 89° 56' E. on a random line between secs. 2 and 11.

40.00 Set a temp.  $\frac{1}{4}$  sec. cor.

80.26 Intersect N. and S. line 9 lks. S. of the cor. of secs. 1, 2, 11 and 12.

Thence I run,

West on a true line between secs. 2 and 11.

Over mountainous land, through heavy timber and dense undergrowth.

Ascend 50 ft. to

2.50 Spur, slopes SW and descend.

25.55 Spring branch, 1 lk. wide, flows SW.

40.13 Set a basalt stone 16 x 8 x 6 ins., 11 ins. in the ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  on N. face, from which

A fir, 24 ins. diam., bears N. 19° E., 46 lks.

dist., marked  $\frac{1}{4}$  S 2 B T.A hemlock, 5 ins. diam., bears S. 35 $\frac{1}{2}$ ° W., 15 lks.dist., marked  $\frac{1}{4}$  S 11 B T.

44.25 North fork of Rock Creek, 75 lks. wide, flows S. about 700 ft. below spur.

46.08 Hunting trail bears N. and S.

50.00 Foot of mountain bears N. and S. and ascend 40 ft. to

53.00 Spur, slopes SE and descend 25 ft. to.

57.00 Spring branch, 2 lks. wide, flows SE and ascend 400 ft. to

80.26 The cor. of secs. 2, 3, 10 and 11.

Land mountainous.

Soil clay loam, 2nd rate.

Timber fir, hemlock, cedar and pine.