

County Surveyor's Record, Douglas County, Oregon

-43-

Subdivisional and Exterior Lines of T. 25 S., R. 2 W., W. M.

CHAINS
79.78

Intersect the N and S line 12 lks. N of the cor. of secs. 14, 15, 22 and 23.

Thence I run,

N.89°55'W on a true line between secs. 15 and 22.

Over mountainous land, through heavy timber and dense undergrowth.

5.00 Descend along SW slope.

32.60 Spring branch, 1 lk. wide, flows N.85°W.

39.89 The point for $\frac{1}{4}$ sec. cor. falls on a basalt stone in place 24 x 10 x 6 ins., above ground at the exact cor. point I marked a cross (X) and $\frac{1}{4}$ to N of cross for $\frac{1}{4}$ sec. cor., from which

A hemlock, 12 ins. diam., bears N.39°W., 7 lks. dist., marked $\frac{1}{4}$ S 15 B T.

A cedar, 8 ins. diam., bears S.18°E., 32 lks. dist., marked $\frac{1}{4}$ S 22 B T.

42.35 Brook, 6 lks. wide, flows NW about 400 ft. below sec. cor. and ascend 300 ft. to

60.00 Spur, slopes NW and descend 250 ft. to

79.78 The cor. of secs. 15, 16, 21 and 22.

Land mountainous.

Soil clay loam, 2nd rate.

Timber fir, hemlock, pine and cedar.

Undergrowth rhododendron, chinquepin, hemlock, fir, hazel, and willow.

Mountainous land or land covered with heavy timber or dense undergrowth. 79.78 chs.

N.2°W between secs. 15 and 16.

Over mountainous land, through heavy timber and dense undergrowth.

Descend.

23.75 Spring branch, 1 lk. wide in ravine 25 ft. deep, flows NW.