

Subdivisional and Exterior Lines of T. 25 S., R. 2 W., W. M.

CHAINS	<p>A fir, 14 ins. diam., bears N.62°W., 31 lks. dist., marked T 25 S R 3 W S 25 B T.</p> <p>bears W 8.49 chs. dist.</p>
442.35	<p>A cor. of secs. 25 and 36 which is a post 4 ins. sq., marked and witnessed as described by the Surveyor General, bears W 9.03 chs. dist.</p>
483.30	<p>The $\frac{1}{4}$ sec. cor. on the E boundary of sec. 36 bears W 9.56 chs. dist.</p>
524.35	<p>The cor. to Tps. 25 and 26 S., R's 2 and 3 W, which is a post 4 ins. sq., marked and witnessed as described by the Surveyor General, bears W. 10.07 chs. dist.</p>

July 25th, 1900.

GENERAL DESCRIPTION

This township is very rough and mountainous throughout, with the exception of a narrow valley along Rock Creek.

The hills are very steep; the ridges sharp and rocky; and the canyons deep and narrow.

The township is heavily timbered throughout with a fairly merchantable quality of fir, hemlock, cedar and pine, with some cottonwood along the larger streams.

The soil of the township is generally quite rocky, although the bottom lands along Rock Creek are rich sandy loam, producing the best of hay, oats, wheat and vegetables and where fruit trees have been planted, they are thrifty and give promise of producing well.

The township is well watered by Rock Creek and its numerous tributaries which afford water sufficient to flume the timber to market.

There is one settler in sec. 15; one in sec. 16; a deserted cabin with small clearing in sec. 21; a settler in sec. 20; two settlers in sec. 29; two in sec. 30; and two in sec. 31.