

County Surveyor's Record, Douglas County, Oregon

Portion of the East Bdy. of T. 25 S., R. 4 E., W. 4

CHAINS	<p>Finding the E. Bdy. of this Township impracticable to be run, made survey as follows:</p> <p>Establishing the proper Sec. and Qr. Sec. Cors. as noted in the field books of Subdivisions.</p> <p>S.0*20'E., bet. secs. 3 and 4.</p> <p>80.83 chains to Cor. of Secs. 3, 4, 9 and 10, Thence South, 5 miles and established Cor. of Secs. 3, 4, 33 and 34, Thence</p> <p>West, on random line on the S. Bdys. of Secs. 33, 32 and 31, at 3 miles and 38 lks. intersect Township Corner.</p> <p>Therefore, the line is correct and the bearing East.</p>	
	<p>North Boundary of T. 26 S., R. 3 W., as surveyed by Addison R. Flint, Deputy Surveyor, under Contract No. 56, dated March 1, 1855.</p>	
	<p>West, on random line on the North Bdy. of Secs. 1, 2, 3, 4, 5 and 6. Set temp. half mile and mile posts at 40.00 and 80.00 chs. and intersected W. Bdy. of Tp. at 5 miles 78 chains and 77 lks. and at a point 390 lks. S. of true Township Corner of Township.</p> <p>Therefore, the correction will be 65 lks. N. per mile. course, S.89*32'E.(of N. Bdy.)</p>	
15.00	<p>East, on true N. Bdy. of Sec. 6. Va.18*30'E.</p> <p>Brook, 8 lks. wide, runs S.</p>	-30
38.77	<p>Set Qr. Sec. post, from which</p> <p style="padding-left: 20px;">A Cedar, 22 ins. diam., bears S.5*W., 150 lks. dist.</p> <p style="padding-left: 20px;">A B. Oak, 6 ins. diam., bears N.10*E., 21 lks. dist.</p>	-20
78.77	<p>Set post cor. to Secs. 31, 32, 5 and 6, from which</p> <p style="padding-left: 20px;">A Dogwood, 5 ins. diam., bears N.17*W., 19 lks. dist.</p> <p style="padding-left: 20px;">A Maple, 5 ins. diam., bears N.55*E., 13 lks. dist.</p> <p style="padding-left: 20px;">A Maple, 6 ins. diam., bears S.31*E., 37 lks. dist.</p> <p style="padding-left: 20px;">A Red Fir, 18 ins. diam., bears S.83*W., 7 lks. dist.</p> <p>Land, 3rd rate.</p> <p>Timber, Fir; scattering Laurel, Cedar, Oak and underbrush.</p>	+80