

East Bdy. of T. 25 S., R. 4 W., W. M.

CHAINS	South, 08'W., on a true line along the East Bdy. of Sec. 36. Va.23'E.	
40.00	Set $\frac{1}{4}$ Sec. post, from which A Fir, 18 ins. diam., bears S.80'E., 7 lks. dist. A Fir, 12 ins. diam., bears S.50'W., 7 lks. dist.	
70.00	Creek, 3 lks. wide, course E.	-250
80.00	To Township Corner.	-250
	July, August 1, 1871.	

Subdivisions of T. 25 S., R. 3 W., W. M., as surveyed by Laban H. Wheeler, Deputy Surveyor, under his Contract No. 467 dated April 7, 1883.

Preliminary to commencing this survey, I run West, on a blank line on the South Bdy. of Sec. 36 at 39.92 chs., found the Qr. Sec. Cor. and at 79.94 chs., found the Sec. Cor. As the East Bdy. of the Township was run with the same Compass and Assistants, it was not re-run. My compass will therefore run the same line as the Exteriors, and the chaining practically agrees.

Survey commenced April 30, 1883, with Burts improved Solar Compass. I commenced at the Corner to Secs. 1, 2, 35 and 36, on South Bdy., which is a post Cor. 4 ins. sq., firmly set in the ground, mkd. T 25 S S 36 on NE., R 3 W S 1 on SE., T 26 S S 2 on SW., S 35 on NW. faces with 5 notches on W., and 1 notch on E. edges from which

A Cedar, 12 ins. diam., bears N.1'E., 22 lks. dist.
mkd. T 25 S R 3 W S 36 B T.

A Red Fir, 20 ins. diam., bears N.39'W., 25 lks. dist.
mkd. T 25 S R 3 W S 35 B T.

A Red Fir, 28 ins. diam., bears S.82'W., 53 lks. dist.
mkd. T 26 S R 3 W S 2 B T.

A Maple, 2 ins. diam., bears S.62'E., 18 lks. dist.
mkd. T 26 S R 3 W S 1 B T.

Thence, I run
North, bet. Secs. 35 and 36. Va.21 $\frac{1}{2}$ 'E.
Through timber.