

## County Surveyor's Record, Douglas County, Oregon

## Subdivisions of T. 25 S., R. 3 W., W. M.

CHAINS		
	<p>Thence, I run S.89°45'W., on true line between Secs. 12 and 13, with same Var.</p>	
39.76	<p>Set Dogwood post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, for <math>\frac{1}{4}</math> Sec. Cor., mkd. <math>\frac{1}{4}</math> S on W. face, from which</p> <p style="padding-left: 40px;">A Fir, 6 ins. diam., bears N.2°W., 18 lks. dist. mkd. <math>\frac{1}{4}</math> S B T.</p> <p style="padding-left: 40px;">A Fir, 8 ins. diam., bears S.16°W., 23 lks. dist. mkd. <math>\frac{1}{4}</math> S B T.</p>	
79.52	<p>The Cor. to Secs. 11, 12, 13 and 14. Land, mountainous. Soil, 3rd rate. Densely covered with forests of Fir, Hemlock, Cedar, Pine, Maple, Alder, Yew, Chinquapin, Laurel and Dogwood. Thick undergrowth of Sallal, Vine maple, Hazel, Manzanita, Fir, Laurel, Salmonberry and Huckleberry.</p> <p style="text-align: right;">May 1, 1883.</p>	
	<p>North, between Secs. 11 and 12.      Var. 21<math>\frac{1}{2}</math>*E. Through timber.</p>	
5.00	Ascend.	
7.18	A Fir, 36 ins. diam.	
17.10	A Hemlock, 40 ins. diam.	
17.30	A brook, 4 lks. wide, course W.	
40.00	<p>Set Hemlock post, 3 ft. long, 3 ins. sq., 24 ins. in the ground, for <math>\frac{1}{4}</math> Sec. Cor., mkd. <math>\frac{1}{4}</math> S on W. face, on ridge, course E. and W., from which</p> <p style="padding-left: 40px;">A Hemlock, 6 ins. diam., bears E. 13 lks. dist. mkd. <math>\frac{1}{4}</math> S B T.</p> <p style="padding-left: 40px;">A Hemlock, 12 ins. diam., bears N.41°W., 14 lks. dist. mkd. <math>\frac{1}{4}</math> S B T.</p>	+1000
59.10	A brook, 8 lks. wide, course SW.	