

County Surveyor's Record, ³⁴Douglas County, Oregon

Subdivisions of T. 25 S., R. 4 W., W. M.

CHAINS		
		Va.20*E.
	East, on random line bet. secs. 24 and 25.	
40.00	Set tem. $\frac{1}{2}$ sec. post.	
79.80	Intersect at post cor. to secs. 24 and 25, on E. Bdy, from which	
	West, on true line bet. secs. 24 and 25.	
18.50	A spring, course S.	-50
39.90	Set $\frac{1}{2}$ sec. post, from which	
	A Cedar, 8 ins. dia., bears N.5*E., 15 lks. dis.	
	A Fir, 6 ins. dia., bears South, 11 lks. dis.	
69.90	Top of ridge, course NE and SW.	+550
79.80	The cor. to secs. 23, 24, 25 and 26.	
	Land, mountainous, 3rd rate.	
	Timber, 2nd rate, principally Fir and Cedar.	
	Underbrush, same.	
		Va.20*E.
	North, bet. secs. 23 and 24.	
40.00	Set $\frac{1}{2}$ sec. post, from which	-300
	A Cedar, 8 ins. dia., bears N.50*W., 15 lks. dis.	
	A Fir, 30 ins. dia., bears S.10*E., 14 lks. dis.	
49.00	A spring, course NE.	-350
80.00	Set post cor. to secs. 13, 14, 23 and 24, from which	-500
	A Fir, 7 ins. dia., bears N.70*E., 29 lks. dis.	
	A Maple, 10 ins. dia., bears S.60*E., 45 lks. dis.	
	A Fir, 10 ins. dia., bears S.5*W., 20 lks. dis.	
	A Cedar, 8 ins. dia., bears N.40*W., 71 lks. dis.	
	Land, 2nd rate, mountainous.	
	Timber, 1st rate, mostly Fir and Cedar, but little underbrush and that the same, with mountain Laurel.	
	August 2, 1871.	
		Va.19*E.
	East, on a random line bet. secs. 13 and 24.	
40.00	Set tem. $\frac{1}{2}$ sec. post.	