

40

## County Surveyor's Record, Douglas County, Oregon

West Bdy. of Tp. 25 S., R. 6 W., W. M. as surveyed by W. H. Byars, Deputy Surveyor, under Contract 272, dated August 22, 1877.

## CHAINS

I established the N. W. cor. of sec. 19, Tp. 25 S., R. 6 W., as per field notes furnished from the Surveyor Generals office, viz.

An Alder, 20 ins. dia., bears N.57 $\frac{1}{2}$ \*W., 96 lks. dis.

A Maple, 14 ins. dia., bears S.66\*W., 153 lks. dis.

A W. Oak, 6 ins. dia., bears S.41\*E., 60 lks. dis.

A Y. Oak, 10 ins. dia., bears N.76 $\frac{1}{2}$ \*E., 90 lks. dis.

Trees all standing as here represented;

From said cor. I run

North, on W. bdy. of sec. 18. Va.18\*E.

30.00 Top of spur, course E. +800

40.00 Set a Fir post, 4 ins. dia., 40 ins. long,  $\frac{1}{3}$  in the ground, from which +100

A Fir, 30 ins. dia., bears N.82\*E., 64 lks. dis.

A Fir, 30 ins. dia., bears N.2\*W., 150 lks. dis.

80.00 Set a Fir post, 36 ins. long, 4 ins. dia.,  $\frac{1}{2}$  in ground for the cor. to secs. 7, 12, 13 and 18, from which +100

A Fir, 20 ins. dia., bears N.60\*E., 33 lks. dis.

A Maple, 8 ins. dia., bears S.80\*W., 35 lks. dis.

A Fir, 16 ins. dia., bears S.28\*E., 50 lks. dis.

A Fir, 60 ins. dia., bears N.68\*W., 50 lks. dis.

Land, broken, rocky, mountainous.

Soil, 3rd rate.

Timberes principally destroyed by fire.

Sept 6, 1877

---

Va.18\*E.

North, on W. Bdy. of sec. 7.

.50 Dry bed of creek, course E.

18.00 Top of spurs, course E. +1000

40.00 Set a maple post 40 ins. long, 3 ins. dia., for  $\frac{1}{2}$  sec. cor., from which +800

A Cedar, 16 ins. dia., bears N.83\*E., 70 lks. dis.

A Fir, 50 ins. dia., bears N.55 \*W., 94 lks. dis.

71.00 Top of mountain, course N.10\*E. +1500