

East Bdy. of Sec. 1, Tp. 25 S., R. 7 W., W. M.

CHAINS

- 80.66 Intersect S. Bdy. of T. 24 S. R 6 W., 22 lks. E. of the SW. cor. of said Tp., which is a post firmly set mkd. and witnessed as described by the Surveyor Gen.
Thence I run
S.0°9'E.; on a true line bet. secs. 1 and 6.
Ascend gradually over nearly level ground through green timber and dense undergrowth.
- 40.66 Set a Cedar post, 3 ft. long, 4 ins. sq., 24 ins. in the ground for $\frac{1}{4}$ sec. cor. mkd. $\frac{1}{4}$ S on N. face, from which
A Fir, 24 ins. dia., bears S.38°E., 64 lks. dis. mkd. $\frac{1}{4}$ S B T.
A Fir, 24 ins. dia., bears S.67°W., 109 lks. dis. mkd. $\frac{1}{4}$ S B T.
- 54.90 Summit of mountain, 75 ft. above sec. cor, bears nearly S., thence descend on E. slope over nearly level ground, 50 ft. to
- 67.30 Summit of same ridge, bears N.10°W., and S.10°E.
- 71.52 A fir, 30 ins. dia., on line. I mark with 2 notches on N. and S. sides.
- 80.66 The cor. to secs. 1, 6, 7 and 12.
Land, mountainous.
Soil, 3rd rate.
Timber, Good Fir and Cedar.
Undergrowth, young Fir, Myrtle, Sallal, Fern, Arrow-wood, and Hazle.
Mountainous land or land covered with dense undergrowth
80.66 chs.

Oct. 5, 1897.

Retracement of E. Bdy. of Sec. 13, T. 25 S., R.7 W.
Same Deputy and Contract.

From the cor. of secs. 13, 18, 19 and 24, I run
North, to retrace E. Bdy. of sec. 13, T. 25 S., R. 7 W.,
Va.20°E..