

North Boundary of T. 26 S., R. 7 W.

CHAINS		
80.00	<p>Set Post Corner Secs. 4, 5, 32 & 33, from which</p> <p>A Fir, 30 ins. diam., bears N.80*E., 28 lks.</p> <p>A Fir, 30 ins. diam., bears S.70*E., 71 lks</p> <p>A Fir, 30 ins. diam., bears N.50*W., 60 lks.</p> <p>A Fir, 12 ins. diam., bears S.85*W., 140 lks.</p> <p>This mile is on the East slope of the Coast Mountains.</p> <p>Soil poor.</p> <p>Timber, Oak and Fir.</p> <p style="text-align: right;">June 11th, 1855</p>	-60
<hr/>		
<p>West. On N. Boundary of Section 5. Va. 19½*E.</p>		
00.05	A Branch, 2 lks. wide, course SE.	-2
15.50	Summit of Ridge, course N.&S.	+500
30.00	A Branch, 2 lks. wide, course NW.	-80
32.90	A Branch, 2 lks. wide, course NW.	-10
40.00	<p>Set ¼ Sec. Post, from which</p> <p>A Fir, 24 ins. diam., bears N.24*E., 16 lks.</p> <p>A Fir, 20 ins. diam., bears S.12*E., 50 lks.</p>	+50
80.00	<p>Set Post Cor. Secs. 5, 6, 31 & 32, from which</p> <p>A Fir, 36 ins. diam., bears N.78*E., 11 lks.</p> <p>A Laurel, 6 ins. diam., bears N.73*W., 12 lks.</p> <p>A Laurel, 10 in. diam., bears S.35*E., 64 lks.</p> <p>A Laurel, 10 in. diam., bears S.62*W., 13 lks.</p> <p>Land uneven.</p> <p>Soil, 3d rate.</p> <p>Timber, fir, cedar, hemlock, laurel, etc.</p>	-500
<hr/>		
<p>West. On North Boundary of Section 6. Va. 19½*E.</p>		
00.54	A Cedar, 24 ins. diam.	-5
11.75	Descend perpendicular rocks 50 feet.	-300
23.25	A Branch, 15 lks. wide, course NW.	-200
40.00	<p>Set ¼ Sec. Post, from which</p> <p>A Fir, 8 ins. diam., bears N.65*W., 8 lks.</p>	+200