

County Surveyor's Record, Douglas County, Oregon

12

Subdivisions of Fractional T. 25 S., R. 7 W.

CHAINS 57.50	Leave Prairie, course NE. and SW.	-50
57.50	Enter scattering Oak Timber.	
68.30	Branch, 2 lks. wide, course South	-20
80.00	To Corner.	+25
	First 25 chains is a deep rocky canyon. Balance is principally a high prairie ridge covered with good grass. Soil, 2d rate.	
	North. Between Sections 33 & 34. Va. 19*E.	
14.00	Enter Fir Timber, course E.&W.	+30
16.00	A Branch, 5 lks. wide, course E.	-10
16.00	Leave Fir and enter oak timber, course E. & W.	
22.50	Leave Timber and enter Prairie, course NW. and NE.	+50
40.00	Set $\frac{1}{4}$ Section Post, from which A B. Oak, 20 ins. diam., bears N.51*W., 146 lks. A B. Oak, 24 ins. diam., bears N. $\frac{1}{2}$ *E., 432 lks.	+100
49.00	Enter Timber, course E.&W.	+50
52.60	A Branch, 6 lks. wide, course East.	-30
53.17	A Branch, 5 lks. wide, course East.	+10
80.00	Set Post Corner Secs. 27, 28, 33 & 34, from which A Laurel, 15 ins. diam., bears N.20*W., 46 lks. A Maple, 9 ins. diam., bears S.40*E., 62 lks. A Fir, 12 ins. diam., bears S. 3*W., 79 lks. A Fir, 12 ins. diam., bears N.84*E., 200 lks. South half rolling ^{and} ^{ed} timber/with oak and fir. Soil, 2d rate. North half on East slope of Coast Mountains rough and rocky.	+600
	East. On Random between Secs. 27 and 34. Va. 18*30' E.	
40.00	Set temporary $\frac{1}{4}$ Section Post.	
80.30	Intersect N.& S. Line at corner.	