

Subdivisions of T. 25 S., R. 7 W.

CHAINS		
40.00	Set temporary $\frac{1}{4}$ Section Post.	
79.70	Intersect N. & S. Line 50 lks. South of Corner. S.89*39'W. On True Line between Secs. 11 & 14.	
.80	A Rock, 4x4 ft. and 6 ft. above ground.	
39.85	Set $\frac{1}{4}$ Sec. Post, from which	-200
	A Laurel, 12 ins. diam., bears N.88*E., 26 lks.	
	A Fir, 12 ins. diam., bears South, 36 lks.	
56.00	Branch, 6 lks. wide, course NW.	-250
66.20	Branch, 2 lks. wide, course N.	+100
79.70	To beginning corner.	+100
	Land, rough.	
	Timber, fir, cedar and hemlock.	
	Undergrowth, laurel and hazel.	
<hr/>		
	North between Secs. 10 & 11.	
		Va. 18*45'E.
13.20	Branch, 5 lks. wide, course West.	-200
40.00	Marked a Laurel, 6 ins. diam. for $\frac{1}{4}$ Sec. post, from which	+500
	A Laurel, 6 ins. diam., bears N.30*E., 18 lks.	
	An Oak, 15 ins. diam., bears West 13 lks.	
40.00	Offset West 50 lks. to avoid a rocky precipice.	
45.00	Offset East to line.	+10
65.65	Branch, 2 lks. wide, course West.	+200
67.50	Branch, 3 lks. wide, course SW.	+10
80.00	Set Post on Summit of mountain, for cor. secs. 2, 3, 10	+200
	and 11, from which	
	A Fir, 24 ins. diam., bears S.10*E., 18 lks.	
	A Fir, 36 ins. diam., bears N.45*W., 11 lks.	
	A Fir, 12 ins. diam., bears S.75*W., 34 lks.	
	A Fir, 12 ins. diam., bears N.88*E., 50 lks.	
	Land, mountainous .	
	Soil, 3d rate.	
	Timber, fir and cedar.	
	Undergrowth, laurel, oak and hazel.	
		July 1st, 1857