

## County Surveyor's Record, Douglas County, Oregon

30

## Subdivisions of T. 25 S., R. 7 W.

CHAINS		
	<p>A Fir, 18 ins. diam., bears N.10*W., 25 lks.  A Fir, 8 ins. diam., bears N.80*E., 5 lks.  Land very hilly. North half open and sparsely timbered,  with oak; balance fir timber.  Soil, 3d rate.</p>	
	<p>North. On Random between Secs. 5 &amp; 6. <span style="float: right;">Va. 19*E.</span></p>	
40.00	Set temporary $\frac{1}{4}$ Section Post.	
79.29	<p>Intersect North Boundary 23 lks. East of corner.  S.0*10'E. On True Line between Secs. 5 &amp; 6.</p>	
39.29	<p>Marked the rocky bed of river where the line runs,  thus "X" from which  A Laurel, 12 ins. diam., bears N.58*E., 140 lks.  A Laurel, 10 ins. diam., bears N.30*E., 270 lks.  No trees convenient West of line.</p>	
54.20	<p>Leave rocky bed of river and marked a Fir 24 ins. diam.,  on right bank for Meander post, from which  A Fir, 40 ins. diam., bears West 10 lks.  A Fir, 12 ins. diam., bears S.10*E., 25 lks.</p>	
54.50	Trail, course NE. and SW.	+10
79.29	To beginning Corner.	+500
	<p>Nearly three quarters of line is along rocky bed of river;  balance hilly, fir timbered land.  Soil 3d rate.  <span style="float: right;">July 4th, 1857.</span></p>	
	<p>West. On Random Line between Secs. 6 &amp; 7.</p>	
40.00	Set temporary $\frac{1}{4}$ Sec. Post.	
80.40	<p>Intersect West Boundary 46 lks. North of corner.  N 89*40'E. On True Line between Secs. 6 &amp; 7.  This corner being at edge of river, left bank, commence  at Meander Post right bank 9.14 chs. South and run  N.89*40'E., 28.27 chs. and North 9.14 chs. to line.</p>	