

Portion of West Boundary of T. 25 S., R. 7 W.

CHAINS

A Fir, 30 ins. diam., bears N.47*E., 25 lks. dist.
 A Fir, 8 ins. diam., bears S.7*E., 29 lks. dist.
 A Fir, 60 ins. diam., bears S.56*W., 64 lks. dist.
 A Maple, 8 ins. diam., bears N.84*W., 25 lks. dist.

Land, hilly, 2nd and 3rd rate.

Narrow bottom along creek 1st rate.

Timber, first rate. x

North, along W. boundary of Sec. 30.

Va 18*E.

1.00	Begin steep ascent.	
9.00	Top of same. E. slope of mountain.	+400
16.00	Top of rocky bluff, a fir, 20 ins. diam.	+600
23.00	Top of spur, course E.	+900
30.00	In deep ravine, course E.	
40.00	Set cedar post for $\frac{1}{4}$ sec. cor. from which	+500
	A Laurel, 10 ins. diam., bears N.82*E., 36 lks. dist.	
	A Laurel, 24 ins. diam., bears N.32*W., 33 lks. dist.	
70.00	Top of ridge, course NE and SW.	+1400
80.00	Set post (fir) for the cor. to secs. 19, 24, 25 and 30	+800
	from which	
	A Fir, 60 ins. diam., bears N.82*E., 25 lks. dist.	
	A Fir, 60 ins. diam., bears S.8*E., 69 lks. dist.	
	A Fir, 14 ins. diam., bears S.82*W., 24 lks. dist.	
	A Fir, 14 ins. diam., bears N.32 $\frac{1}{2}$ *W., 22 lks. dist.	

Land, high broken, rocky, mountainous, 3rd rate.

Timber, same species, very poor.

June 10, 1874.

Subdivisions of T. 25 S., R. 7 W. W. M. Same Deputy and Contract.

Begin at the established cor. to secs. 16, 17, 20 and 21
 in Tp. 25 S. Range 7 W. and run South on a true line
 between secs. 21 and 20.

Va. 18*E.