

43

Retracement of a portion of East boundary of T. 25 S., R. 8 W., as surveyed by A. R. and S. C. Flint, Deputy Surveyors, under contract no. 392 dated May 26, 1881.

CHAINS

Commenced at SE cor. of T 25 S R 8 W and ran N on E

boundary of sec. 36, witness trees,

Hemlock, 10 ins. diam., bears N.30\*W., 30 lks. dist.

Hemlock, 18 ins. diam., bears S.12\*W., 8 lks. dist.

Hemlock, 24 ins. diam., bears S.80\*E., 24 lks. dist.

Fir, 20 ins. diam., bears N.15\*E., 36 lks. dist.

6.68 A Fir, 18 ins. diam. Va. 18½\*E.

16.00 Hubbard Creek, 50 lks. wide, course NE.

21.00 Hubbard Creek, 50 lks. wide, course NW.

25.50 Hubbard Creek, 50 lks. wide, course N.10\*E.

40.00 ¼ post gone, witness trees found. Made a new post, 3 ft.

long, 3 ins. sq. from which

A Maple, 6 ins. diam., bears N.8\*E., 25 lks. dist.

A Yew, 10 ins. diam., bears S.25\*W. 52 lks. dist.

80.00 Cor. to secs. 25, 36, 30 and 31. Post standing and

in good condition. Witness trees,

A Fir, 30 ins. diam., bears N.47\*E., 25 lks. dist.

A Fir, 8 ins. diam., bears S.7\*E., 29 lks. dist.

A Fir, 60 ins. diam., bears S.56\*W., 64 lks. dist.

A Maple, 8 ins. diam., bears N.84\*W., 25 lks. dist.

North, on E boundary of sec. 25.

Va 18\*E.

1.00 Begin steep ascent.

9.00 Top of same, E slope of mountain.

16.00 Rocky bluff, a Fir, 20 ins. diam.

23.00 Summit of spur, course E.

30.00 In deep ravine, course E.

40.00 Cedar ¼ post, with witness trees, viz.

A Laurel, 10 ins. diam., bears N.82\*E., 36 lks. dist.

A Laurel, 24 ins. diam., bears N.32\*W., 33 lks. dist.

70.00 Summit of ridge, course NE and SW.

81.20 Cor. to secs. 24, 25, 19 and 30. Post and witness trees found and in good condition.

A Fir, 60 ins. diam., bears N.82\*E., 69 lks. dist.

A Fir, 60 ins. diam., bears S.8\*E., 69 lks. dist.

25 p. 3890