

Portion of E boundary of T. 25 S., R. 7 W. <sup>8</sup>

CHAINS

- A Fir, 60 ins. diam., bears N.82\*E., 69 lks. dist.
- A Fir, 60 ins. diam., bears S.8\*E., 69 lks. dist.
- A Fir, 14 ins. diam., bears S.82\*W., 24 lks. dist.
- A Fir, 14 ins. diam., bears N.32½\*W., 22 lks. dist.

North, on true line between secs. 24 and 19.

Va 18 ¾\*E

- 2.00 Fir tree, 7 ft. in diam.
- 23.45 Creek, 4 lks. wide, course W.
- 35.10 Creek, 2 lks. wide, course NW.
- 40.00 Set fir ¼ post, 3 ft. long, 3 ins. sq. from which
  - A Cedar, 20 ins. diam., bears S.80\*W., 22 lks. dist.
  - A Cedar, 18 ins. diam., bears N.53\*E., 18 lks. dist.
- 80.00 Cor. to secs. 18, 19, 13 and 24. Set fir post, 4 ft. long, 4 ins. sq. from which
  - A Fir, 16 ins. diam., bears N.25\*E., 5 lks. dist.
  - A Fir, 14 ins. diam., bears S.82\*E., 19 lks. dist.
  - A Fir, 36 ins. diam., bears S.40\*W., 20 lks. dist.
  - A Fir, 14 ins. diam., bears N.85\*W., 33 lks. dist.

Land, 3rd rate.

Timber, good and plenty.

August 26, 1881

North, on true line between secs. 13 and 18.

Va 18 ¾\*E

- 27.80 Spring branch, 3 lks. wide, course NE.
- 40.00 Set cedar ¼ post, 3 ft. long 3 ins. sq. on the N slope of canyon from which
  - A Hemlock, 10 ins. diam., bears N.42\*E., 11 lks. dist.
  - A Hemlock, 8 ins. diam., bears S.85\*W., 5 lks. dist.
- 42.00 A creek, 10 lks. wide, course SW.
- 68.10 Creek, 1 lk. wide, course SW.