

47

Retracement of a portion of The North Bdy. of T. 26 S., R. 7 W.

CHAINS

West, on N bdy. of sec. 5.

Va 19*30'E.

- .15 Stream, 2 lks., course SE.
- 15.55 Summit of coast range mountains.
- 30.00 Stream, 2 lks. wide, course NW.
- 33.00 Stream, 2 lks. wide, course NW.
- 40.00 $\frac{1}{2}$ post and witness trees probably destroyed by fire, made new post, 3 ft. long, 3 ins. sq. and set firmly in the ground, from which a
 - A Fir, 24 ins. diam., bears N.24*E., 16 lks. dist.
 - A Fir, 20 ins. diam., bears S.12*E., 50 lks. dist.
- 80.38 Cor. to sec. 5, 6, 31 and 32. Post rotted down. Witness trees all standing. Made new cedar post, 40 ins. long 4 ins. sq. set firmly in the ground from which
 - A Fir, 36 ins. diam., bears N.78*E., 11 lks. dist.
 - A Laurel, 6 ins. diam., bears N.73*W., 12 lks. dist.
 - A Laurel, 10 ins. diam., bears S.35*E., 64 lks. dist.
 - A Laurel, 10 ins. diam., bears S.62*W., 13 lks. dist.

West, on N bdy. of sec. 6.

Va 19*30'E.

- .54 Cedar, 24 in. diam.
- 11.75 Descend point rocks.
- 23.35 Stream, 15 lks. wide, course NW.
- 40.45 Found old post, decayed and down, also found witness trees, made and set a fir post, 3 ft. long, 4 ins. sq. from which
 - A Fir, 8 ins. diam., bears N.65*W., 8 lks. dist.
 - A Cedar, 36 ins. diam., bears S.45*W., 9 lks. dist.
- 52.95 Stream, 1 lk. wide, course NW.
- 79.75 Tp. cor to 25 and 26. Rs. 7 and 8 W. Post found and in good condition, witness trees also found viz.,
 - A Hemlock, 10 ins. diam., bears N.30*W., 30 lks. dist.
 - A Hemlock, 18 ins. diam., bears S.12*W., 8 lks. dist.
 - A Hemlock, 24 ins. diam., bears S.80*E., 24 lks. dist.
 - A Fir, 20 ins. diam., bears N.15*E., 36 lks. dist.

June 28, 1881.