

Subdivisions of T, 25 S., R. 7 W., W. M.

CHAINS

S.89*26E on a true line making my random a true line.
Ascend from cor.

10.90 Summit of ridge, 60 ft. above cor. bears N and S, thence descend.

24.20 Small branch, course N 200 ft. below ridge.

39.40 Set a fir post 3 ft. long, 4 ins. sq. 24 ins. in the ground for 1/2 sec. cor marked 1/2 S on N face from which
A Fir, 16 ins. diam., bears N.13*W., 27 lks. dist. marked 1/2 S B T.

A Fir, 20 ins. diam., bears S.59*W., 33 lks. dist. marked 1/2 S B T.

51.40 Summit of ridge, 100 ft. above small branch.

54.40 Branch of 2 lks. wide, course N.60 ft. below ridge.

79.40 The cor. of secs. 17, 18, 19 and 20.

Land, mountainous.

Soil, 3rd rate.

Timber, Fir, Madrona, and Cedar.

Undergrowth, Arrowwood, Pigeon Berry, Salal and Briars.

Mountainous land, or covered with dense undergrowth

79.40 chs.

Nov. 5, 1896.

To complete the survey in the NE part of this Tp. I commence at the SW cor. of sec. 13 which is a white oak still standing marked T 25 S S 13 on NE., R 7 W S 24 on SE., S 23 on SW and S 14 on NW faces, no notches from which

A White Oak, 24 ins. diam., bears N.18*E., 285 lks. dist. marked T 25 S R 7 W other marks overgrown.

A White Oak, 24 ins. diam., bears S.70*E., 175 lks. dist. marks obliterated.

I find no witness trees SW of this cor.

A White Oak, 14 ins. diam., bears N.20*W., 275 lks. dist. marks overgrown.