

65

Subdivisions of T. 25 S., R 7 W., W. M.

WEST COAST PRINTING & BINDING CO., PORTLAND 1876

CHAINS

Thence I run
 S.89*47'E. to retrace the S bdy. of sec. 13.
 Descend from cor.
 24.50 Stream 6 lks. wide, course S. 150 ft. below cor. Ascend.
 40.10 $\frac{1}{2}$ sec. cor. N of my line 7 lks.
 60.00 Summit of ridge, course N and S.
 80.25 Intersect N and S line, 2 lks. S. of cor. of sec. 13
 and 18, 19 and 24. This line therefore bears N.89*48'
 W., and S.89*48'E.
 Land, mountainous.
 Soil, 4th rate.
 Timber, Fir and Oak.
 Undergrowth Oak, Fir and briars.
 Mountainous land, or land covered with dense under-
 growth, 80.25 chs.

Nov. 6, 1896.

From the cor. of secs. 13, 18, 19 and 24, I run
 N. to retrace E bdy. of sec. 13, T 25 S R 7 W.
 Va 20'E.

Ascend from cor, 750 ft. to
 30.00 Summit of ridge.
 40.00 $\frac{1}{2}$ sec. cor gone. Witness trees still standing but
 markings overgrown.
 80.10 Intersect E and W line 20 lks. E. of cor. to secs. 7,
 12, 13 and 18, which is a fir post still standing
 marked and witnessed as described by the Surveyor
 General.
 This line therefore bears N.9*W., S.9'E.
 I find no irregularities in the S and E boundaries.
 Land, mountainous.
 Soil, 4th rate, very rocky.
 Timber, Fir, Oak, and Madrona, of but little value.
 Undergrowth, hazel, Arrowwood, Pigeon berry, briars, fern.
 Mountainous land, land covered with dense undergrowth.
 80.10 chs.

Nov. 6, 1896.