

County Surveyor's Record, Douglas County, Oregon

66

Subdivisions of T 25 S., R. 7 W., W. M.

CHAINS

I now go to the cor. of secs. 11, 12, 13 and 14, which is a cross (x) on a rock about 4 x 2 x 2 ft. and witnessed as described by the notes of the Surveyor General.

Thence I run

S.89°48'E. on a random line between secs. 12 and 13.

Va 20°E.

40.00 Set temp $\frac{1}{4}$ sec. cor.

80.15 Intersect E bdy. of Tp. 25 lks. S. of cor. to secs. 13, 18, 7 and 12, heretofore described.

Thence I run

N.89°59'W on a true line, between secs. 12 and 13.

Ascend gradually from cor.

7.00 Dry gulch course, N. Ascend rocky ridge.

24.00 A Fir, 18 ins. diam. on line, 1 mark with 2 notches on E and W sides.

38.00 Summit of ridge, course N and S. 800 ft. above cor. a trail bears N and S. Descend.

40.07 Set a fir post 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor marked $\frac{1}{4}$ S on N face from which
 A Fir, 16 ins. diam., bears S.37°E., 80 lks. dist. marked $\frac{1}{4}$ S B T.
 A Fir, 14 ins. diam., bears N.9°E., 48 lks. dist. marked $\frac{1}{4}$ S B T.

80.15 The cor. to secs. 11, 12, 13 and 14, 700 ft. below trail. Land, mountainous.
 Soil, 4th rate.
 Timber, a poor quality of Fir, Cedar and Hemlock.
 Undergrowth Fir, Hemlock, Arrowwood, and Briars.
 Mountainous land, or land covered with dense undergrowth. 80.15 chs.

Nov. 7 1896.