

County Surveyor's Record, Douglas County, Oregon

68

Subdivisions of T. 25 S., R. 7 W., W. M.

CHAINS	<p>Heavily timbered with Fir, Hemlock and Cedar. Undergrowth Fir, Hemlock, Salal, Hazel and Briars. Mountainous land, or land covered with dense undergrowth 80.00 chs.</p> <p style="text-align: right;">Nov. 7, 1896.</p>
*	
	<p>S.89°59'E. on a random line between secs. 1 and 12. Va 20*4</p>
40.00	Set temp. $\frac{1}{4}$ sec. cor.
79.85	Intersect E bdy. of the tp at the cor. of secs. 1, 6
	7 and 12, which is a marked and witnessed as
	described by the Surveyor General.
	thence 1 run
	N.89°59'W. on a true line between secs. 1 and 12. Va 20°E.
	Descend from cor.
12.00	Branch 4 lks. wide, course N. 400 ft. below cor. Ascend.
22.00	Summit of ridge, 275 ft. above branch bears N and S. Descend.
34.00	A branch, 5 lks. wide, course N. 270 ft. below ridge. Ascend.
39.92	Set a cedar post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face from which A Fir, 15 ins. diam., bears N.30°E., 47 lks. dist. marked $\frac{1}{4}$ S B T. A Fir, 12 ins. diam., bears S.26°E., 52 lks. dist. marked $\frac{1}{4}$ S B T.
52.50	Summit of ridge, 600 ft. above branch bears N and S Descend.
57.50	Dry gulch, course N.
79.85	the cor. to secs. 1, 2, 11 and 12. Land, mountainous.