County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 3 W.

CHAINS	
31.50	Summit of ridge SE. & NW. (800 ft.)
40.00	Set temp. ¼ sec. cor.
54.50	Creek 3 lks. wide course NW.
79.00	Intersect E. boundary Tp. 9 lks. S. of cor. to secs. 18, 19, 13 & 24
	Thence I run S.89*56'W. on true line bet. secs. 13 & 24
39.50	Set a fir post for ¼ sec. cor. 3 ft. long and 3 ins. sq. from which a
	Fir, 12 ins. diam., bears N.10*W. 14 lks. dist.
	Fir, 10 ins. diam., bears S.75*E. 9 lks. dist.
79,00	Cor. to secs. 13, 14, 23 & 24
	Land 3 rd rate
	Timber, fir, laurel, cedar, hemlock & myrtle
	Undergrowth same as last mile
	Sept. 5, 1881
	North, on true line bet. secs. 13 & 14
	Var. 19*E.
19.10	Summit of ridge E. & W.
23.40	Creek 3 lks. wide course NW.
40.00	Set ¼ post 3 ft. long & 4 ins. sq. from which a
	Fir, 10 ins. diam., bears S.30*E. 9 lks. dist.
	Fir, 12 ins. diam., bears N.80*W. 27 lks. dist.
42.25	Creek 25 lks. wide course NE.
50.00	Spring branch
80.00	Cor. to secs. 11, 12, 13 & 14
	Set hemlock post 4 ft. long & 4 ins. sq. from which a
	Fir, 10 ins. diam., bears S.40*E. 10 lks. dist.
	Fir, 8 ins. diam., bears N.30*E. 9 lks. dist.
	Fir, 14, ins. diam., bears N.45*W. 16 lks. dist.
	Fir, 20 ins. diam., bears S.35*W. 9 lks. dist.
	Land 3rd rate high and broken
	Timber, fir, cedar, hemlock, laurel & maple
	Undergrowth, fir, vine maple & hazle