

20
Subdivisions of T. 25 S., R. 8 W.

CHAINS

Commenced to ascend ridge

40.00

Set a fir $\frac{1}{4}$ post 3 ft. long and 3 ins. sq. from which a
Hemlock, 20 ins. diam., bears N.35*W. 12 lks. dist.
Fir, 14 ins. diam., bears N.85*E. 56 lks. dist.

40.20

Creek 4 lks. wide course SE.

51.50

Summit of ridge E. & W.

80.00

Cor. to secs. 21, 22, 27, & 28

Set post 4 ft. long and 4 ins. sq. from which a
Fir, 30 ins. diam., bears N.35*E. 18 lks. dist.
Dogwood, 10 ins. diam., bears S.15*E. 24 lks. dist.
Hemlock, 20 ins. diam., bears S.65*W. 66 lks. dist.
Fir, 36 ins. diam., bears N.45*E. 39 lks. dist.

Land 3rd rate

Timber good, fir, hemlock, cedar & laurel

Undergrowth fir, vine maple, hazle, etc.

East, on random line between secs. 22 & 27

Var. 19*E.

1.50

Creek 3 lks. wide course NW.

12.00

Summit of ridge NE. & SW.

22.50

Rocky ravine course SE.

40.00

Set temp. $\frac{1}{4}$ sec. post

79.15

Intersect line 75 lks. S. from cor. to secs. 22, 23, 26 & 27

Thence I run S.89*28'W. on true line bet. secs. 22 & 27

39.57

Set lime oak $\frac{1}{4}$ post 3 ft. long and 3 ins. sq. from
which a

Fir, 42. ins. diam., bears S.10*W. 32 lks. dist.

Fir, 30 ins. diam., bears N.10*W. 58 lks. dist.

79.15

Cor. to secs. 21, 22, 27 & 28

Land 3rd & 4th rate--high broken & rocky

Timber fir, hemlock, cedar, & laurel

Undergrowth fir, vine maple, hazle & salal bushes

Sept. 23, 1881