

County Surveyor's Record, Douglas County, Oregon

22
Subdivisions of T. 25 S., R. 8 W.

CHAINS 79.16	<p>Cor. to secs. 15, 16, 21 & 22</p> <p>Land 3rd & 4th rate</p> <p>Timber fir, hemlock, cedar, laurel & maple</p> <p>Undergrowth fir, vine maple, hazle</p> <p style="text-align: right;">Sept. 24, 1881</p>
	<p>North, on true line between secs. 15 & 16</p> <p style="text-align: right;">Var. 19$\frac{1}{4}$*E.</p>
19.27	Stream 10 lks. wide course E.
32.50	Ascend ridge
40.00	<p>Set fir $\frac{1}{4}$ sec. post 3 ft. long & 3 ins. sq. from which a</p> <p style="padding-left: 40px;">Laurel, 12 ins. diam., bears N.50*E. 2 lks. dist.</p> <p style="padding-left: 40px;">Fir, 7 ins. diam., bears S.25*W. 16 lks. dist.</p>
44.50	Summit of ridge NE. & SW.
72.00	Stream 8 lks. wide course NE.
80.00	<p>Cor. to secs. 9, 10, 15 & 16</p> <p>Set a fir post 4 ft. long & 5 ins. sq. from which a</p> <p style="padding-left: 40px;">Fir, 10 ins. diam., bears N.50*W. 9 lks. dist.</p> <p style="padding-left: 40px;">Dogwood, 6 ins. diam., bears N.80*E. 14 lks. dist.</p> <p style="padding-left: 40px;">Fir, 30 ins. diam., bears S.45*W. 53 lks. dist.</p> <p style="padding-left: 40px;">Fir, 20 ins. diam., bears S.70*E. 21 lks. dist.</p> <p>Timber good and plenty--hemlock, fir, cedar & laurel</p> <p>Undergrowth fir, vine maple, and hazle</p> <p>Land 3rd & 4th rate -- rough</p>
	<p>East, on random line between secs. 10 & 15</p> <p style="text-align: right;">Var. 19*E.</p>
9.26	Stream 5 lks. wide course E.
31.40	Stream 4 lks. wide course E.
40.00	Set temp. $\frac{1}{4}$ sec. post
79.18	<p>Intersect line 62 lks. S. of cor. to secs. 10, 11, 14</p> <p style="padding-left: 40px;">& 15</p> <p>Thence I run S.89*34'W. on true line bet. secs. 10 & 15</p>
39.09	<p>Set fir $\frac{1}{4}$ sec. post 3 ft. long & 3 ins. sq. from which a</p> <p style="padding-left: 40px;">Fir, 14 ins. diam., bears S.5*E. 15 lks. dist.</p>