

County Surveyor's Record, Douglas County, Oregon

23

Subdivisions of T. 25 S., R. 8 W.

CHAINS	
79.18	<p>Fir, 24 ins. diam., bears N.40*E. 20 lks. dist. Cor. to secs. 9, 10, 15 & 16. Land 3rd & 4th rate--broken & rocky Timber fir, hemlock, cedar & laurel Undergrowth vine maple, fir, hazle & salal bushes Sept. 25, 1881</p>
<p>North, on true line between secs. 32 & 33 Var. 19*E.</p>	
10.50	Summit of ridge or spur NE. & SW.
16.56	Creek 3 lks. wide course SE.
29.50	Summit of ridge SE. & NW.
40.00	<p>Set yew $\frac{1}{2}$ post 3 ft. long & 3 ins. sq. from which a Hemlock, 16 ins. diam., bears S.65*E. 10 lks. dist. Hemlock, 14 ins. diam., bears S.15*W 23 lks. dist.</p>
41.25	Creek 5 lks. wide course SE.
55.00	Summit of ridge SE. & NW.
61.47	<p>Bluff of rocks. Offset $\frac{1}{2}$ W. 100 lks. Thence N. 350 lks. Thence E. 100 lks. to line</p>
70.50	Summit of ridge or spur E. & W.
80.00	<p>Cor. to secs. 28, 29, 32 & 33 Set cedar post 4 ft. long 4 ins. sq. from which a Hemlock, 14, ins. diam., bears S.10*W. 22 lks. dist. Hemlock, 18 ins. diam., bears S.68*E. 45 lks. dist. Hemlock, 24 ins. diam., bears N.50*W. 21 lks. dist. Hemlock, 10 ins. diam., bears N.40*E. 17 lks. dist. Land 3rd rate Timber fir, hemlock, etc.</p>
<p>East, on random line between secs. 28 & 33 Var. 19*E.</p>	
15.10	Creek 15 lks. wide course SE.
40.00	Set temp. $\frac{1}{2}$ sec. post
47.50	Summit of ridge NE. & SW.
81.00	<p>Intersect line 75 lks. S. of cor. to secs. 27, 28, 33 & 34</p>