

County Surveyor's Record, Douglas County, Oregon

24
Subdivisions of T.25 S., R. 8 W.

CHAINS	<p>Thence I run S.89*28'W. on true line between secs. 28 & 33</p>
40.50	<p>Set cedar post for $\frac{1}{2}$ sec. cor. 3 ft. long and 3 ins. sq. from which</p> <p style="padding-left: 40px;">A hemlock, 10 ins. diam., bears S.75*E. 10 lks. dist.</p> <p style="padding-left: 40px;">A hemlock, 36 ins. diam., bears N.30*W. 19 lks. dist.</p>
81.00	<p>Cor. to secs. 28, 29, 32 & 33</p> <p>Land 3rd & 4th rate--broken & rocky</p> <p>Timber fir, hemlock, cedar & laurel</p> <p>Undergrowth fir, vine maple, hazle & salal bushes</p> <p style="text-align: right;">Sept. 27, 1881</p>
	<hr/> <p>North, on true line between secs. 28 & 29</p> <p style="text-align: right;">Var. 19$\frac{1}{2}$*E.</p>
0.60	Summit of spur NE. & SW.
13.75	Creek 10 lks. wide course E.
26.50	Summit of ridge NE. & SW.
33.65	Stream 6 lks. wide course SE.
40.00	<p>Hemlock tree 6 ins. diam., for $\frac{1}{2}$ sec. cor. witness trees</p> <p style="padding-left: 40px;">A fir, 24 ins. diam., bears N.85*W. 20 lks. dist.</p> <p style="padding-left: 40px;">A fir, 30 ins. diam., bears N.70*E. 25 lks. dist.</p>
42.00	Summit of ridge SE. & NW.
51.25	Creek 5 lks. wide course NE.
66.50	Summit of ridge SE. & NW.
79.90	Creek 10 lks. wide course SE.
80.00	<p>Cor. to secs. 20, 21, 28 & 29</p> <p>Set hemlock post 4 ft. long & 4 ins. sq. firmly in the ground from which</p> <p style="padding-left: 40px;">A cedar, 16 ins. diam., bears S.70*W. 23 lks. dist.</p> <p style="padding-left: 40px;">A hemlock, 24 ins. diam., bears N.86*W. 89 lks. dist.</p> <p style="padding-left: 40px;">A cedar, 14 ins. diam., bears S.60*E. 91 lks. dist.</p> <p style="padding-left: 40px;">A cedar, 18 ins. diam., bears N.10*E. 100 lks. dist.</p> <p>Land 3rd rate</p> <p>Timber & undergrowth as usual</p> <p style="text-align: right;">Sept. 29, 1881</p>