

## County Surveyor's Record, Douglas County, Oregon

15

## Subdivisions of T. 25 S., R. 8 W.

CHAINS	East, on random line between secs. 21 & 28 Var. 19*E.
1.50	Creek 15 lks. wide course S.
8.50	Summit of ridge or spur NE. & SW.
15.47	Summit of ridge or spur NE. & SW.
30.00	Summit of ridge SE. & NW. (Coos Bay trail)
40.00	Set temp. $\frac{1}{4}$ sec. post
55.50	Creek 5 lks. wide course N.
80.96	Intersect line 35 lks. S. from cor. to secs. 21, 22, 27 & 28 Thence I run S.89*45'W. on true line between secs. 21 & 28
40.48	Set dogwood $\frac{1}{4}$ sec. post 3 ft. long & 3 ins. sq. from which A maple, 10 ins. diam., bears N.50*E. 35 lks. dist. A fir, 36 ins. diam., bears S.35* E. 43 lks. dist.
80.96	Cor. to secs. 20, 21, 28 & 29 Land 3rd rate high broken and rocky Timber fir, cedar, hemlock, laurel & maple Undergrowth fir, vine maple, hazle & salal bushes Oct. 1, 1881
	North on true line between secs. 20 & 21 Var. 19*E.
2.50	Creek 15 lks. wide course SE.
18.00	Summit of ridge E. & W.
26.25	Stream 10 lks. course SW. rocky ravine
28.50	Bluff rocks--perpendicular 75 ft. high
34.00	Creek 3 lks. wide course SE.
37.00	Bluff rocks 40 ft. high through which was a crevice large enough to pass
40.00	Set oak $\frac{1}{4}$ post 3 ft. long 3 ins. sq. from which A laurel, 8 ins. diam., bears S.60*E. 15 lks. dist. A fir, 30 ins. diam., bears N.60*W. 26 lks. dist.
44.75	Summit of ridge SE. & NW.