

17
Subdivisions of T. 25 S., R. 8 W.

CHAINS

General Description

This township is similar in soil and timber to the other fractional townships we have surveyed.

The ridges and canyons (as a general thing) are quite as sharp and deep as any we have had; and particularly in the west and north west parts of the township the cliffs of rock are equal if not worse than any we have had to contend with this summer.

There are strong indications of coal in several localities--one in section 14 when the outcroppings are visible and by good judges said to be of a superior quality.

East Boundary of T. 25 S., R. 9 W.,

As surveyed by Charles L. Campbell, Deputy Surveyor,
Under Contract No. 747, dated May 5, 1902

From the corner of Tps. 25 & 26 S., Rs. 8 & 9 W., which is a post firmly set in the ground, marked and witnessed as described by the surveyor general.

I run

N. between secs. 31. & 36.

Descend into Arrow Creek, through heavy timber and undergrowth, along steep E. slope

8.75 Foot of descent, 200 ft. below sec. cor., bears N.30*W. and S.30*E.

8.80 Dry bed of Arrow Creek, 5 lks. wide course S.30*E.

Ascend S. slope of mountain

29.75 Top of ridge, 500 ft. above Arrow Creek bears N.60*W. S.60*E.

Descend into ravine

40.00 Set a sandstone 28x12x12 ins., 21 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on the W. face from which
A cedar, 16 ins. diam., bears N.64 $\frac{1}{2}$ *E. 64 lks. dist. marked $\frac{1}{4}$ S 31 B T
A cedar, 24 ins. diam., bears S.79 $\frac{3}{4}$ *W. 75 lks. dist.
marked $\frac{1}{4}$ S 36 B T