

36

Retracement of the S. Bdy. of T. 25 S., R. 8 W.

CHAINS

S. face from which

A cedar, 10 ins. diam., bears S.83°E., 25 lks. dist.
marked $\frac{1}{4}$ S 5 B T

A hemlock, 10 ins. diam., bears N.20°E., 10 lks. dist.
marked $\frac{1}{4}$ S 32 B T

The true course of this line is N.89°57'W., and the
length is 39.40 chs.

80.15 Fall 5 lks. S. of the cor. of secs. 5, 6, 31 and 32,
which is a badly decayed post, marked and witnessed
as described by the Surveyor General. I reestablish
this cor. as follows: I destroy the old cor. and at
the exact point, set a fir post, 3 ft. long, 4 ins.
sq., 24 ins. in the ground, marked T 25 S S 32 on NE.,
R 8 W S 5 on SE, T 26 S S 6 on SW., and S 31 on NW.
face; with 5 notches on E. and 1 notch on W. edge;
from which

A fir, 28 ins. diam., bears N.70°E., 65 lks. dist.
marked T 25 S R 8 W S 32 B T

A fir, 42 ins. diam., bears S.10°E., 33 lks. dist.
marked T 26 S R 8 W S 5 B T

A fir, 34 ins. diam., bears S.10°W., 40 lks. dist.
marked T 26 S R 8 W S 6 B T

A fir, 72 ins. diam., bears N.8°W., 100 lks. dist.
marked T 25 S R 8 W S 31 B T

The true course of this line, from the $\frac{1}{4}$ sec. cor., is
N. 89°58'W., and the length is 40.75 chs.

July 14, 1911

At the corner of secs. 5, 6, 31, and 32 on S. bdy. of
the Tp.,

I run

West, retracing line, bet. secs. 6 and 31

40.15 Old $\frac{1}{4}$ sec. cor., bears S. 10 lks. dist., being a post
firmly set, marked and witnessed as described by the
Surveyor General. The true course of this line is S.
89°51'W. and the length is 40.15 chs.