

## County Surveyor's Record, Douglas County, Oregon

48

Retracement and Resurvey of Subdivisional Lines, T. 25 S., R. 8 W.

CHAINS

on S. face from which

A fir, 24 ins. diam., bears N.42\*30'E., 12 lks. dist.  
marked  $\frac{1}{2}$  S 16 B T

A fir, 16 ins. diam., bears S.16\*30'W. 37 lks. dist.  
marked  $\frac{1}{2}$  S 21 B T

No trace of cor. or of sec. line can be found after  
diligent search. (See Method of Procedure ).

Descend through heavy timber, and dense undergrowth

71.53 Creek, 6 lks. wide, course N.80\*E.

Ascend steep ridge

80.88 Set a fir limb post 3 ft. long, 4 ins. sq. 24 ins. in  
the ground, for cor. of secs. 16 and 21, marked T 25  
S S 16 on NE., R 8 W S 21 on SE. faces; with 3 notches  
on S. and 3 notches on N. edges from which

A fir, 30 ins. diam., bears N.68\*30'E. 27 lks. dist.  
marked T 25 S R 8 W S 16 B T

A fir, 12 ins. diam., bears S.86\*30'E. 38 lks. dist.  
marked T 25 S R 8 W S 21 B T

After diligent search I can find no trace of sec. cor.  
or of connecting sec. lines. (See Method of Procedure).

Land, mountainous.

Soil; 2nd and 3rd rate

Timber, heavy fir, hemlock and cedar

Dense undergrowth, little fir, hemlock and rhododendron.

Mountainous land, covered with heavy timber and dense  
undergrowth and exceptionally difficult to survey  
80.88 chs.

July 5, 1911

At the cor. of secs. 4, 5, 32 and 33 on the S. Bdy. of  
the Tp., which is a badly decayed post, marked and  
witnessed as described by the Surveyor General. I  
reestablish as follows: I destroy old cor., and at  
exact point set a fir post, 3 ft. long, 4 ins. sq.,  
24 ins. in the ground, for cor. of secs. 4, 5, 32  
and 33 marked T 25 S S 33 on NE., R 8 W S 4 on SE.,