

## County Surveyor's Record, Douglas County, Oregon

50

Retracement and Resurvey of Subdivisional Lines, T. 25 S., R. 8 W.

CHAINS

Land, mountainous

Soil, 2nd and 3rd rate

Timber, heavy fir, hemlock and cedar

Mountainous land, covered with heavy timber and dense undergrowth, and exceptionally difficult to survey  
83.01 chs.

July 6, 1911

At the cor. of secs. 28 and 33

Thence I run

North on retracement of West bdy. of sec. 28

Along side of rocky mountain, in heavy timber and dense undergrowth of little fir and hemlock, exceptionally difficult to survey.

No further trace of old survey line

40.00 Almost impassable jungle of small fir, hemlock and fallen burnt timber; no trace of  $\frac{1}{4}$  sec. cor.

At this cor. I set off  $22^{\circ}40'N.$  on the decl. arc; and observe the sun on the meridian; the resulting lat. is  $43^{\circ}22'N.$

79.90 Find evidences of old cor. of secs. 21 and 28, 10 lks.

W. Post destroyed; bearing trees badly decayed, otherwise marked and witnessed as described by the Surveyor General. Set new cedar post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for cor. of secs. 21 and 28, marked T 25 S S 21 on NE., R 8 W S 28 on SE., with 2 notches on S. and 4 notches on N. from which

A fir, 48 ins. diam., bears  $N.85^{\circ}E.$  56 lks. dist.  
marked T 25 S R 8 W S 21 B T

A cedar, 15 ins. diam., bears  $S.0^{\circ}30'E.$  84 lks. dist.  
marked T 25 S R 8 W S 28 B T

The true course of this line is  $N.0^{\circ}4'W.$  and the dist. is 79.90 chs.

Land, mountainous

Soil, 2nd and 3rd rate