

County Surveyor's Record, Douglas County, Oregon

61

Extension Survey of
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

81.48 Intersect E. bdy. of sec. 10, 7 lks. S. of cor. of secs.
3, 4, 9 and 10

Thence I run
S.89°40'W. on true line, bet. secs. 4 and 9

Ascend through heavy timber and dense undergrowth, ex-
ceptionally difficult to survey

3.58 Crest of spur, bears N. and S.

Descend

17.00 Wolf creek, 10 lks. wide, course SE.

Ascend

41.48 Set a fir limb post, 3 ft. long, 4 ins. sq. 24 ins. in
the ground, for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ S 4 on N. and
9 on S. face; from which

A fir, 32 ins. diam., bears S.33°30'E. 80 lks. dist.
marked $\frac{1}{4}$ S 9 B T

A fir, 36 ins. diam., bears N.52°30'E. 156 lks. dist.
marked $\frac{1}{4}$ S 4 B T

47.03 Dry creek bed, course NE.

Ascend through heavy timber and dense undergrowth

65.08 Top of ridge, bears N. and S.

Descend

78.78 Creek, 4 lks. wide, course SE.

Ascend

81.48 The cor. of secs. 4 and 9

Land, mountainous

Soil, 2nd and 3rd rate

Timber, heavy fir, hemlock, alder and cedar

Dense undergrowth, vine maple, salal and small fir

Mountainous land, covered with heavy timber and dense
undergrowth, and exceptionally difficult to survey

81.48 chs.

August 4, 1911

At the cor. of secs. 4 and 9

Thence I run
N.0°02'W. bet. secs. 4 & 5