

County Surveyor's Record, Douglas County, Oregon

64
Extension Survey of
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

A fir, 16 ins. diam., bears N.85°E. 26 lks. dist.
marked $\frac{1}{2}$ S 32 B T

A fir, 34 ins. diam., bears N.0°30'W. 72 lks. dist.
marked $\frac{1}{2}$ S 31 B T

Ascend steep mountain through heavy timber and brush

43.50 Top of ridge, bears NE. and SW.

Descend

66.00 Creek, 2 lks. wide, course NE.

Ascend

66.90 Point of rocky ridge, slopes E.

Descend

69.50 Creek, 2 lks. wide, course SE.

Ascend

76.20 Top of ridge, bears SE. and NW.

80.00 Set yew post, 3 ft. long, 4 ins. sq. 24 ins. in the
ground for cor. of secs. 29, 30, 31 and 32 marked T
25 S S 29 on NE., R 8 W S 32 on SE., S 31 on SW. and
S 30 on NW. faces; with 1 notch on S. and 5 notches on
E. edges from which

A cedar, 28 ins. diam., bears N.67°50'E. 27 lks.
dist., marked T 25 S R 8 W S 29 B T

A cedar, 24 ins. diam., bears S.20°10'E. 47 lks. dist.
marked T 25 S R 8 W S 32 B T

A cedar, 18 ins. diam., bears S.20°15'W. 50 lks. dist.
marked T 25 S R 8 W S 31 B T

A cedar, 50 ins. diam., bears N.32°10'W. 18 lks. dist.
marked T 25 S R 8 W S 30 B T

Land, mountainous

Soil, 2nd and 3rd rate

Timber, heavy fir, cedar, hemlock, alder and madrone

Undergrowth, vine maple, rhododendrons, small fir and
hemlock

Mountainous land, covered with heavy timber and dense
undergrowth, and exceptionally difficult to survey

80.00 chs.

July 22, 1911