

County Surveyor's Record, Douglas County, Oregon

67

Extension Survey of
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

- 40.00 Set hemlock post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 30 on N. and 31 on S. faces from which
- A hemlock, 10 ins. diam., bears S.6*E.26 lks. dist. marked $\frac{1}{4}$ S 31 B T
- A hemlock, 18 ins. diam., bears N.8*W. 35 lks. dist. marked $\frac{1}{4}$ S 30 B T
- 57.00 Top of ridge, bears NE. and SW.
Descend
- 60.00 Dry canyon, course S.
Ascend
- 67.40 Top of ridge, bears N. and S. trail, along ridge
Descend
- 80.37 Intersect the E. bdy. of T. 25 S., R. 9 W., 4.00 chs N. 0*13'E. from the cor. of secs. 25 and 36, previously described. At point of intersection, I set a fir post 3 ft. long, 4 ins. sq. 24 ins. in the ground, for closing cor. for secs. 30 and 31, marked C C T 25 S R 8 W on E., S 30 on N. and S 31 on S. faces; with 1 groove on S. and 5 grooves on N. faces; from which
- A fir, 30 ins. diam., bears N.26*40'E. 32 lks. dist. marked T 25 S R 8 W S 30 B T
- A fir, 48 ins. diam., bears S.58*20'E. 16 lks. dist. marked T 25 S R 8 W S 31 B T
- Land, mountainous
Soil, rocky; 3rd rate
Timber, fir, hemlock, madrone and cedar
Dense undergrowth, little fir, hemlock, rhododendron and poison ivy.
Mountainous land, covered with heavy timber and dense undergrowth, and exceptionally difficult to survey,
80.37 chs.

July 24, 1911

At the cor. of secs. 29, 30, 31 and 32