

County Surveyor's Record, Douglas County, Oregon

70
Extension Survey of
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

40.00 Set hemlock post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 20 on N. and 29 on S. face; from which

A fir, 24 ins. diam., bears N.75*E. 113 lks. dist. marked $\frac{1}{4}$ S 20 B T

A fir, 30 ins. diam, bears S.86*30'E. 79 lks. dist. marked $\frac{1}{4}$ S 29 B T

46.75 Top of ridge, bears NW. and SE.
Descend

48.00 Rim rock, 80 ft. high, bears N. and S.

79.10 Creek, 10 lks. wide, course SE.
Ascend through burnt timber and dense underbrush.

80.75 Intersect the W. Bdy. of Sec. 28, 2.90 chs. S.0*04'E., from the cor. of secs. 21 and 28, recently reestablished by me. At point of intersection, I set a cedar post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, for closing cor. of secs. 20 and 29, marked C C T 25 S R 8 W on W., S 29 S. and S 20 on N. faces; with 2 grooves on S. and 4 grooves on N. faces; from which

A cedar, 30 ins. diam., bears S.39*W. 21 lks. dist. marked T 25 S R 8 W S 29 B T

A cedar, 20 ins. diam., bears N.43*W. 39 lks. dist. marked T 25 S R 8 W S 20 B T

Land, mountainous
Soil, 2nd and 3rd rate
Timber, largely burnt, fir hemlock, cedar and madrone
Dense undergrowth, little fir, hemlock and rhododendron.
Mountainous land, covered with heavy timber and dense undergrowth and exceptionally difficult to survey,
80.75 chs.

July 26, 1911

At the cor. of secs. 19, 20, 29 and 30

Thence I run

West, bet. secs. 19 and 30