

## County Surveyor's Record, Douglas County, Oregon

72

Extension Survey of  
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

Timber, fir, hemlock, cedar, madrone and alder  
Dense undergrowth little fir, hemlock, rhododendron and  
salal.

Mountainous land, covered with heavy timber and dense  
undergrowth and exceptionally difficult to survey,  
79.75 chs.

July 27, 1911

At the cor. of secs. 19, 20, 29 and 30

Thence I run

N.0\*2'W. bet. secs. 19 and 20

Descend through heavy timber and dense little fir ex-  
ceptionally difficult to survey.

20.30 Creek, 2 lks. wide, course NW.; ascend

28.70 Top of ridge, bears NW. and SE.; descend

34.65 Creek 1 lk. wide course NW.

40.00 Set a fir post, 3 ft. long 4 ins. sq. 24 ins. in the  
ground for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S 19 on W. and 20 on  
E. faces, from which

A fir, 20 ins. diam., bears N.1\*0'E. 44 lks. dist.  
marked  $\frac{1}{4}$  S 20 B T

A fir, 24 ins. diam., bears S.39\*30'W. 31 lks. dist.  
marked  $\frac{1}{4}$  S 19 B T

52.00 Top of main divide and Coos Bay Trail, course NW. and SE.

57.40 Top of main divide and Bend in Coos Bay Trail, course  
NW. and SW. Desc.

64.00 Canon, course NW.

74.00 Creek, 1 lk. wide, course NE;

Ascend steep ridge, in dense timber and brush

80.00 Set a dogwood post, 3 ft. long, 4 ins. sq. 24 ins. in  
the ground, for cor. of secs. 17, 18, 19 and 20,  
marked T 25 S S 17 on NE., R 8 W S 20 on SE., S 19  
on SW. and S 18 on NW. faces; with 3 notches on S.  
and 5 notches on E. edges; from which

A fir, 32 ins. diam., bears N.6\*30' E. 43 lks. dist.  
marked T 25 S R 8 W S 17 B T