

## County Surveyor's Record, Douglas County, Oregon

Extension Survey of  
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

A rhododendron, 5 ins. diam., bears S.1\*30'E., 25  
lks. dist., marked T 25 S R 8 W S 20 B T

A hemlock, 15 ins. diam., bears S.68\*30'W. 15 lks.  
dist., marked T 25 S R 8 W S 19 B T

A cedar, 25 ins. diam., bears N.85\*W., 34 lks. dist.  
marked T 25 S R 8 W S 18 B T

Land, mountainous

Soil; 2nd and 3rd rate

Timber, heavy fir, hemlock, cedar and madrone

Dense undergrowth of little fir, hemlock and rhododendron

Mountainous land, covered with heavy timber and dense  
undergrowth and exceptionally difficult to survey,  
80.00 chs.

July 28, 1911

At the cor. of secs. 17, 18, 19 and 20

Thence I run

East, bet. secs. 17 and 20

Descend steep slope, through dense timber and underbrush,  
exceptionally difficult to survey.

5.90 Creek, 1 lk. wide, course NE.; ascend

12.70 Point of ridge, slopes N.; descend

19.40 Creek, 2 lks. wide, course NW.; ascend

33.00 Point of ridge, slopes SW.; descend

36.20 Dry canyon, course SW.; ascend

39.80 Point of ridge, slopes SW.; descend

40.00 Set fir post, 3 ft. long, 4 ins. sq. 24 ins. in the  
ground, for  $\frac{1}{4}$  sec. cor. marked  $\frac{1}{4}$  S 17 on N. and 20 on  
S. face; from which

A fir, 12 ins. diam., bears S.10\*E. 30 lks. dist.  
marked  $\frac{1}{4}$  S 20 B T

A cedar, 15 ins. diam., bears N.20\*W. 75 lks. dist.  
marked  $\frac{1}{4}$  S 17 B T

50.75 Point of ridge, slopes SW.

60.50 Point of ridge, slopes NE. and SW.; descend