

County Surveyor's Record, Douglas County, Oregon

79

Extension Survey of
Subdivisional Lines of T. 25 S., R. 8 W.

CHAINS

and salal.

Mountainous land, covered with heavy timber and dense undergrowth, and exceptionally difficult to survey, 81.30 chs.

August 8, 1911

At the cor. of secs. 7, 8, 17 and 18

Thence I run

N.0*2'W. bet. secs. 7 and 8

Descend steep ridge, through heavy timber and dense undergrowth, exceptionally difficult to survey.

17.50 Dry canon, course East

22.50 Main branch of Lake Creek, 15 lks. wide, course NW.

30.30 Creek, 1 lk. wide, course W.

40.00 Set fir post, 3 ft. long, 4 ins. sq. 24 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S 7 on W. and 8 on E. faces; from which

A hemlock, 20 ins. diam., bears S.15*E. 77 lks. dist. marked $\frac{1}{4}$ S 8 B T

A maple, 28 ins. diam., bears N.20*W. 12 lks. dist. marked $\frac{1}{4}$ S 7 D T

40.60 Creek, 2 lks. wide, course W.; ascend

54.50 Top of ridge, bears E. and W.; descend

61.75 Creek, 2 lks. wide, course W.

65.50 Creek, 2 lks. wide, course W.

72.40 Dry canon, course NW.; ascend

74.25 Top of ridge, bears E. and W. descend

78.25 Creek, 3 lks. wide, course SW.; ascend

80.00 Set a fir post, 3 ft. long, 4 ins. sq. 24 ins. in the ground, for cor. of secs. 5, 6, 7 and 8, marked T 25 S S 5 on NE., R 8 W S 8 on SE., S 7 on SW. and S 6 on NW. faces; with 5 notches on S. and 5 notches on E. edges; from which

A fir, 72 ins. diam., bears N.16*10'E. 103 lks. dist. marked T 25 S R 8 W S 5 B T