

County Surveyor's Record, Douglas County, Oregon

North Boundary of T. 26 S., R. 9 W., W. M.,

CHAINS

from which;

A hemlock 10 ins. diam., bears N.65*E., 28 lks.

dist. marked T 25 S R 9 W S 32 B T.

A fir, 36 ins. diam., bears S.43*E. 41 lks. dist.

marked, T 26 S R 9 W S 5 B T.

A hemlock, 11 ins. diam., bears S. 8*W. 23 lks.

dist. marked, T 26 S R 9 W S 6 B T.

A fir, 20 ins. diam., bears N.10*W. 21 lks.

dist. marked, T 26 S R 9 W S 31 B T.

Land, mountainous.

Soil, 2nd. rate.

Timber, fir, hemlock, maple, myrtle, cedar and
laurel.

Heavy timber and dense undergrowth.

Mountainous or heavily timbered land, or land covered
with dense undergrowth. 56.11 chs.

East

On a true line bet. secs. 5 and 32

Va. 19*15'E.

Descend hill from cor. bears NW. and SE.

10.00

Foot of hill, bears NW. and SE.

-100

23.00

Descend.

Hill bears NW and SE.

40.00

Set hemlock, post 3 ft long 4 ins sq 24 ins., in the
ground for $\frac{1}{4}$ sec. cor. marked, $\frac{1}{4}$ S. on N. face;
from which,

-500

A hemlock, 26 ins. diam., bears N.43*W. 45 lks.

dist marked $\frac{1}{4}$ S B T.A hemlock 24 ins diam., bears S.61*W., 56 lks. dist.,
marked, $\frac{1}{4}$ S B T.

52.70 Brook 8 lks. wide, runs SE.

-125