

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 9 W. W. M.,

CHAINS

A fir, 36 ins. diam., bears S.53 $\frac{1}{2}$ *E., 32 lks. dist.,
marked T 25 S R 9 W S 36 B T.

A fir, 28 ins. diam., bears S.50 $\frac{1}{2}$ *W., 31 lks. dist.,
marked T 25 S R 9 W S 35 B T.

A spruce, 20 ins. diam., bears N.84 $\frac{1}{2}$ *W., 59 lks.
dist., marked T 25 S R 9 W S 26 B T.

This sec. cor. stands about 550 ft. below summit of
divide.

Land, mountainous.

Soil, sandy and gravelly; 2nd. and 3rd. rate.

Timber, 1st. half mile, scattering small firs, spruce and
laurel, last half mile, heavy fir, and hemlock with
some spruce and cedar.

Undergrowth, laurel, small firs, huckleberry and thorns.

Mountainous or heavily timbered lands. 80.00 chs.

East, on a random line bet. secs. 25 and 36.

40.00 Set temp. $\frac{1}{4}$ sec. cor.

79.96 Intersect E. bdy. of the T. 5 lks. N. of the cor. of sec.
25, 30, 31 & 36, described heretofore.

Thence I run N.89*58'W. on a true line bet. secs. 25 & 36.
descend along N. slope of mountain through heavy timber
and dense undergrowth.

2.05 A fir, 38 ins. diam., on line, I mark with 2 notches on
E. and W. sides.

10.60 Ravine, 300 ft. deep, course N.10*W., Spring Branch, 1 lk.
wide in ravine.

Ascend steep E. slope.

18.50 More gradual ascent.

26.00 Ridge point, 300 ft. high, course N. and S.

Descend into canyon.

27.00 Perpendicular Bluffs, 30 ft. high, bear N. and S.

A fir, 30 ins. diam., on line, I mark with 2 notches on
E. and W. sides.

39.98 Set a sandstone, 24x24x14 ins., 18 ins. in the ground,