

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 25 S., R. 9 W. W. M.

CHAINS	
	Thence I run, S.89*53'W. on a true line bet secs. 15 and 22.
	Ascend gradually E. slope of mountain, through heavy timber and dense undergrowth.
24.50	Ravine, 100 ft. deep, course S.
28.10	Spring branch, 2 lks. wide, in ravine 150 ft. deep, course S.70*E.
33.45	A fir, 36 ins. diam., on line, I mark with 2 notches on E. and W. sides.
40.09	Marked a cross on a ledge 20x20x1 ft. above ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N. side of cross; from which, A fir, 56 ins., diam., bears N.30*E. 53 lks. dist. marked $\frac{1}{4}$ S 15 B T. A fir, 36 ins. diam., bears S.40*E., 35 lks. dist. marked $\frac{1}{4}$ S 22 B T.
50.00	Summit of divide bet. Fall Creek and Bottom Creek, 1300 ft. above Bottom Creek, bears N.70*E & S.70*W. Descend gradually along NW. slope of divide.
68.25	Ridge point, descends toward the N. 150 ft. below summit of main divide. Descend steep NW slope.
80.18	The cor. of secs. 15, 16, 21 and 22. Land, rolling and mountainous. Soil, gravelly, 3rd. rate. Timber, fir, hemlock and maple. Undergrowth, laurel, vine maple and sallow. Mountainous, or heavily timbered lands, 80.18 chs. Heavy rains prevents further work until after Oct. 30.
	October 28, 1902
29.20	At the cor. of secs. 15, 16, 21 and 22. Thence I run, N.0*02'W. bet secs. 15 and 16. Descend NW. slope of mountain into Fall Creek, through heavy timber and dense undergrowth. Spring branch, 2 lks. wide, in ravine, 150 ft. deep, course N.70*W.