

County Surveyor's Record, Douglas County, Oregon

Subdivisions of T. 26.S., R. 1 W., W. M.

CHAINS 17.25	Creek, 3 lks. wide, course NE.
24.15	Creek, 1 lk. wide, course NE.
39.92	Set a conglomerate stone 18 x 8 x 6 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ on N face, from which A cedar, 14 ins. diam., bears N.71*W., 23 lks. dist., marked $\frac{1}{4}$ S 20 B T. A cedar, 8 ins. diam., bears S.22*W., 43 lks. dist., marked $\frac{1}{4}$ S 29 B T.
52.50.	Ridge bears N and S. Descend W slope.
79.84	The cor. of secs. 19, 20, 29 and 30. Land mountainous. Soil stony, 3rd and 4th rate. Timber fir, hemlock and cedar; undergrowth vine maple and hemlock.
	West between secs. 19 and 30. Over mountainous land, heavily timbered and covered with dense undergrowth.
0.10	Creek, 3 lks. wide, course N.10*W. Ascend NE slope.
10.50	Ridge point descending N. Descend NW slope.
18.25	Foot of steep descent.
23.15	A cabin (abandoned) bears S. 30 lks. dist.
23.70	Log fence bears N and S.
28.40	Creek, 5 lks. wide, course N. Ascend NE slope.
40.00	Set a conglomerate stone 18 x 8 x 6 ins., 12 ins. in the ground for $\frac{1}{4}$ sec. cor., marked $\frac{1}{4}$ on N face, from which A cedar, 16 ins. diam., bears N.52*E., 24 lks. dist., marked $\frac{1}{4}$ S 19 B T. A cedar, 24 ins. diam., bears S.73*W., 41 lks. dist., marked $\frac{1}{4}$ S 30 B T.